

Item #	Building	Floor Tiles (& mastic)	Above Ceiling Fire Proofing	Mudded Pipe Fittings	Ceiling Tiles	Pipe Insulation
7	12. Johnson Hall - Constructed 1959					
8	Ground Floor	Abated	No	Abated	No	Abated
9	First Floor	Abated	No	Abated	No	Abated
10	Second Floor	Abated	No	Abated	No	Abated
11	Third Floor	Abated	No	Abated	No	Abated

Mechanical Rooms	Gasket Material	Window Caulking Glazing	Transite	Dry Wall Compound	Crawl Space	Fire Doors
N/A	N/A	Abated	No	Abated	Abated	Abated
N/A	N/A	Abated	No	Abated	N/A	Abated
N/A	N/A	Abated	No	Abated	N/A	Abated
N/A	N/A	Abated	No	Abated	N/A	Abated