

Item #	Building	Floor Tiles (& mastic)	Above Ceiling Fire Proofing	Mudded Pipe Fittings	Ceiling Tiles	Pipe Insulation
8	43. Onondaga - Constructed 1972					
9	First Floor	Yes	No	PACM	No	PACM
10	Second Floor	Yes	No	PACM	No	PACM
11	Third Floor	Abated	No	PACM	Abated	PACM
12	Fourth Floor	Abated	No	PACM	Abated	PACM
13	Fifth Floor	Abated	No	PACM	Abated	PACM

Mechanical Rooms	Gasket Material	Window Caulking	Transite	Dry Wall Compound	Crawl Space	Fire Doors
Abated	PACM	N/A	N/A	PACM	N/A	Yes
N/A	PACM	N/A	N/A	PACM	N/A	Yes
N/A	PACM	N/A	N/A	PACM	N/A	Yes
N/A	PACM	N/A	N/A	PACM	N/A	Yes
N/A	PACM	N/A	N/A	PACM	N/A	Yes