

Item	Building	Floor Tiles (& mastic)	Above Ceiling Fire Proofing	Mudded Pipe Fittings	Ceiling Tiles	Pipe Insulation	Mechanical Rooms	Gasket Material
1	1. Gym - East - Constructed 1958							
2	Basement	Abated	No	Abated	No	Abated	Abated	Abated
3	Ground Floor	Abated	No	PACM	No	PACM	Abated	Abated
4	First Floor	Abated	No	PACM	No	PACM	N/A	Abated

<b>Window Caulking</b>	<b>Transite</b>	<b>Dry Wall Compound</b>	<b>Crawl Space</b>	<b>Fire Doors</b>
Abated	No	Abated	Abated	Abated
Abated	No	Abated	Abated	Yes
Abated	No	Abated	Abated	Abated